

## 21-033837-071 (RECEPTACLE ADAPTER)

Transition Adapter, Receptacle, Quadrax  
Type High Speed, 90° Attachment to Board,  
Installation Instructions

See table on reverse side for quadrax cable recommended and crimping tool information.


- A 1. Cut cable for assembly of transition adapter receptacle.
- B 1. Strip cable jacket to expose cable outer braid as illustrated. Ends must be cut cleanly and at right angles to the axial plane of the cable. Cable must not be deformed while making cuts.
- C 1. Slide crimp bushing, large diameter end first, over cable braid until cable jacket butts inside shoulder of crimp bushing.
- D 1. Flair cable braid back over crimp bushing as illustrated to expose inner wires. Trim excess cable braid.
2. Cut off any inner braids, wraps or cable fillers as close to outer cable braid as possible.
3. Cut inner wires to dimension shown. All wires must be cut to equal length. It may be helpful to cut one wire to length. Then, one at a time, cut remaining wires to equal length as the first wire.
- E 1. Strip inner wires to expose center conductors as illustrated. All wires must be stripped to equal length.
- F 1. Carefully splay inner wires perpendicular to the axis of the cable as illustrated.
2. Assemble inner contact over cable center conductor until fully seated against inner wire insulation. Observe center conductor through the contact's wire inspection hole, to make certain conductor is properly positioned.
3. Crimp inner contact to center conductor using crimp tools listed in table on back. Repeat steps F2 and F3 until all inner contacts are crimped.
- G 1. Position rear insulator against cable braid as illustrated. Make certain insulator slots are aligned with splayed inner contact wires. One-by-one, position wired inner contacts inside the insulator slots as shown. The inner contact's retention shoulder must be positioned in front of the insulator's front surface as illustrated.

Continued on back

L-2119-AI  
July 2010


FSCM77820

## 21-033837-071 (RECEPTACLE ADAPTER)



**21-033837-071 (RECEPTACLE ADAPTER)**

- H
1. With inner contacts positioned inside rear insulator slots, assemble front insulator over the inner contacts as shown. The front insulator must butt the rear insulator and the inner contact retention shoulders must enter the front insulator bores.
  2. Observe the front insulator's keyway. When the inner assembly is held as shown in View H, the S1 inner contact is positioned as shown in View H, and when fully assembled, S1 will connect to tail position T1 shown in View I. S2 through S4 will connect to their corresponding tail T2 through T4.
- I
1. Align front insulator keyway with the outer contact's rivet key. Slide the inner contact assembly inside the outer contact assembly until fully seated.
  2. Crimp outer contact body in the area indicated using crimp tools listed in table below.



| Amphenol Part Number | Description  | Twinax Cable Recommended           | Inner Crimp Tools |             | Outer Crimp Tools |                    |
|----------------------|--|------------------------------------|-------------------|-------------|-------------------|--------------------|
|                      |  |                                    | Tool (Setting)    | Positioner  | Tool              | Die Set (Location) |
| 21-033837-071        | Quadrax Transition Adapter Receptacle, 90° Attachment to Board (150 Ohm) | Tensolite 26473/02006X-4 (150 Ohm) | M22520/2-01 (4)   | M22520/2-34 | M22520/5-01       | M22520/5-45 (A)    |

**Amphenol**

Amphenol Aerospace  
 40-60 Delaware Avenue  
 Sidney, New York 13838-1395  
 Website: [www.amphenol-aerospace.com](http://www.amphenol-aerospace.com)