

Instructions

Notification of obsolete contact numbers for MIL-5015 Connectors.

1. The following items are obsolete:
Socket 7527650 and Pin 7527651.
2. When repair is required for the connectors which use these items, such connectors shall be replaced by connectors which utilize the following components:
Socket, Ordnance part number 7527648
Pin, Ordnance part number 7527649

L-2121
May, 2005

Amphenol Aerospace

AMPHENOL CORPORATION
Amphenol Aerospace
40-60 Delaware Avenue
Sidney, New York 13838-1395
www.amphenol-aerospace.com